

# Oil Field Environmental Incident Summary

**Incident:** 20160302155422      **Date/Time of Notice:** 03/02/2016 15:54

**Responsible Party:** North Country

**Well Operator:** EOG RESOURCES, INC.

**Well Name:** PARSHALL 13-26H

**Field Name:** PARSHALL

**Well File #:** 17051

**Date Incident:** 3/1/2016      **Time Incident:** 17:00

**Facility ID Number:**

**County:** MOUNTRAIL

**Twp:** 152

**Rng:** 90

**Sec:** 26

**Qtr:**

**Location Description:** Incident occurred on the Risan Fresh Water Depot, located immediately west of the Parshall 13-26H production facility.

**Submitted By:** Brenda Vaness

**Received By:**

**Contact Person:** Tony Pedersen  
7258 38th St. NW  
Parshall, ND 58770

**General Land Use:** Well/Facility Site

**Affected Medium:** Well/Facility Soil

**Distance Nearest Occupied Building:**

**Distance Nearest Water Well:**

**Type of Incident:** Truck Overflow

**Release Contained in Dike:** Yes - On Facility Site

**Reported to NRC:** No

	Spilled	Units	Recovered	Units	Followup	Units
Oil						
Brine			4	Barrels		
Other	2	Barrels	2	Barrels	2	barrels

**Description of Other Released Contaminant:**

Manufactured saltwater/heavy water

**Inspected:**

**Written Report Received:** 3/9/2016

**Clean Up Concluded:** 3/2/2016

**Risk Evaluation:**

N/A

**Areal Extent:**

**Potential Environmental Impacts:**

N/A

**Action Taken or Planned:**

A hydro vac truck sucked up the standing fluid and contaminated soil, and affected material will be disposed of.

**Wastes Disposal Location:** Liquids and solids taken to disposal.

**Agencies Involved:** TAT  
MHA

**Updates**

---

**Date:** 3/4/2016      **Status:** Reviewed - Assigned to Other Agency      **Author:** Souder, Taylor

**Updated Oil Volume:**

**Updated Salt Water Volume:**

**Updated Other Volume:**

**Updated Other Contaminant**

**Notes:**

The release is within MHA Nation. Report forwarded to MHA Environmental, BIA, and EPA.